

WHAT TO EXPECT:

Your Gem Supply service technician will arrive on your site and evaluate your machine, with you and available operator(s). The technician will run diagnostics to determine performance status, and how machine has been used. The service technician will also complete a PM checklist to include : all inspected parts, functions, and any included parts replaced.

Example:

A battery unit would have the following inspections made:

- Batteries/cables inspected, specific gravity checked, batteries filled, and cables cleaned and treated if necessary.
- Amp draw checked on all motors using an OTC meter.
- Machine lubed at grease points and pivots.
- Filters inspected, cleaned and/or replaced if necessary.
- Vacuum system and hoses checked and cleaned if necessary.
- Pressures checked (tires, head-down, etc.)
- Squeegees removed, cleaned, rotated, adjusted and/or replaced.
- Skirts checked, adjusted and/or replaced as needed.
- Brush/pad motors and hubs inspected, lubed and cleaned if needed.
- Solution system tested and checked for leaks.
- All mechanical functions inspected, lubed and adjusted as necessary.
- All safety functions inspected and adjusted as required.
- Test run machine to ensure optimum performance.
- Machine wiped clean.
- Machine operation and necessary recommendations made with you and available operators. A copy of the checklist and status report will be left.

A propane unit would have the the additional inspections made:

- CO Test performed, as a safety measurement and machine performance check.
- Belts inspected.
- Fluids checked, topped off, or changed as needed.

Any machine within or outside these categories, may also have additional checklists based on different manufactures recommended maintenance schedules.

Planned Maintenance Price

\$159⁰⁰

Call 800-422-9886 to schedule your PM

The PM price is per maintenance call. Gem recommends one visit per quarter. All PM's are guaranteed and include adjustments, lubrication, labor, and trip charge. Propane units include oil and filter, if needed.



SUPPLY

www.gemsupply.net